SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-14EXML27-501	DATE : 2014-06-25
SUBJECT : SENSOR CLUSTER MALFUNCTION(DTC:C123C)		<DESTINATION/MODEL> (As per attached sheet 1) <M/Y> 13-15
GROUP : REAR AXLE(Gr:27)		OUTLANDER/OUTLANDER PHEV(GF0W)

1. Description :

Please refer to the attached document for the correction of the error in writing existing in the applicable service manual.

2. Affected service manuals :

Please refer to the attached document (Attached sheet 1)

3. About the details :

Please refer to theattached document (Attached sheet 2)

MMNA

Applicable manual	Pub. No.	Applicable title (INFO ID)
2014 OUTLANDER Service Manual	MSCD-007B-2014 Mexico: DRAFT	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01900-01)
2015 OUTLANDER Service Manual	MSCD-007B-2015 Mexico: DRAFT	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01900-01)

EU/RUSSIA

Applicable manual	Pub. No.	Applicable title (INFO ID)
2013 OUTLANDER Workshop Manual	CGFE13E1-CD (English) CGFS13E1-CD (Spanish) CGFF13E1-CD (French) CGFG13E1-CD (German) CGFI13E1-CD (Italian) Russia: N/A	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01900-01)
2014 OUTLANDER/ OUTLANDER PHEV Workshop Manual	CGFE14E2-CD (English) CGFS14E2-CD (Spanish) CGFF14E2-CD (French) CGFG14E2-CD (German) CGFI14E2-CD (Italian) Russia: N/A	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01900-01)
2014.5 OUTLANDER/ OUTLANDER PHEV Workshop Manual	CGFE14E3-CD (English) CGFS14E3-CD (Spanish) CGFF14E3-CD (French) CGFG14E3-CD (German) CGFI14E3-CD (Italian) Russia: N/A	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01901-01)

G.EXP/GCC

Applicable manual	Pub. No.	Applicable title (INFO ID)
2014 OUTLANDER Workshop Manual	PWRE1303R (English) PWRS1304R (Spanish)	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01901-01)

MMAL/NZ

Applicable manual	Pub. No.	Applicable title (INFO ID)
2013 OUTLANDER Workshop Manual	AU900304 (MMAL) DRAFT (NZ)	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01900-01)

CHINA

Applicable manual	Pub. No.	Applicable title (INFO ID)
2013 OUTLANDER Workshop Manual	DRAFT	Code No.C123C: Sensor Cluster Malfunction (M274-01-060-01900-01)

Attached sheet 2

STEP 5. Check of hydraulic unit (integrated with G and yaw rate sensor) installation status.

Check that the hydraulic unit (integrated with G and yaw rate sensor) is installed correctly <Refer to GROUP 35C – Hydraulic unit (integrated with G and yaw rate sensor) >.

Q: Is the check result normal?

YES : Go to Step 6

NO : Reinstall the hydraulic unit (integrated with G and yaw rate sensor) correctly. Then go to Step 6.

STEP 6. M.U.T.-III data list.

Check the following data list.

- Item No.22: Yaw rate sensor
- Item No.23: Lateral G sensor

<Deleted>

Q: Is the check result normal?

YES : Go to Step 7

NO : Replace the hydraulic unit (integrated with G and yaw rate sensor) ~~is installed correctly~~ (Refer to GROUP 35C – Hydraulic unit (integrated with G and yaw rate sensor)). Then go to Step 11.

STEP 7. Check of steering wheel sensor installation status.

Check that the steering wheel sensor is installed correctly (Refer to GROUP 35C – Steering Wheel Sensor).

Q: Is the check result normal?

YES : Go to Step 8

NO : Install the steering wheel sensor correctly. Then go to Step 8.