Newsletter	**ENL-19-010-SR_IO**
Model	**Outlander PHEV (GG2W)**
Group	**15**
Subject	**Replacement of air flow sensor on Outlander PHEV**
Date	**02-05-2019**
	(REF. MMC: SSI 1902002)

RECALL CAMPAIGN

Campaigns are issued by MME to ensure the systematic rectification of design, construction or manufacturing defects. It is the Distributor's responsibility to implement and follow an adequate procedure to ensure that any Recall and Service Campaign information is made available to the Dealers without delay, and that Dealers will carry out the campaign as instructed.

Normal newsletters only require action on customer complaint basis.
A revised newsletter supersedes the previous release as from the revised date.

For additional information and responsibilities please refer to the After Sales Policies & Warranty Procedures Manual.

Contact:
Mitsubishi-motors-europe.com

© Copyright Mitsubishi Motors Europe B.V. 2019

ENL-19-010-SR_IO
Issue date: 02 May 2019

1. CONDITION:

In case the EV system warning light illuminates, it might be the cause that the IC engine may not start. If the engine is running while the warning light illuminates and if it keeps running without charging the battery, the vehicle will run out of battery and finally cannot be driven.

2. CAUSE:

Due to low sulfidation corrosion resistance of the air flow sensor, and due to the sulfur gas evaporation from the intake rubber hose, the internal resistor of the air flow sensor might corrode and disconnect.

3. AFFECTED MODEL RANGE:

Models	:	Outlander PHEV (GG2W)
VIN / Chassis number	:	MY14*
Markets concerned	:	All markets

* Your vehicle might not be included, please confirm with an authorized Mitsubishi dealer.

4. PRODUCTION FIX:

Since February, 2014 the air flow sensor is changed to high a sulfidation corrosion resistance version.

5. FIELD FIX:

Repair procedure

Replace the air flow sensor with countermeasure part according to the workshop manual procedures.

Required parts

Vehicle	Part number	Part name	Quantity	Remarks
Outlander PHEV (GG2W)	MW400254	Sensor, air flow	1	-

6. WARRANTY REIMBURSEMENT:

Please visit our authorized Mitsubishi workshop. The repair will be carried out by the authorized Mitsubishi Workshop free of charge for the customer.

Operation	Vehicle model	Order number	Operation time	Remarks
Air flow sensor replacement	Outlander PHEV (GG2W)	R30380 20	0.3H	-

7. PART SUPPLY:

The parts will be supplied via the Mitsubishi dealer network.