MITSUBISHI MOTORS

SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-10E42-502	DATE : 2010-10-20
SUBJECT : ENGINE SWITCH INSPECTION		<MODEL> (EUR/RUSSIA) ASX (GA0W) <M/Y> 11
GROUP : KEYLESS OPERATION SYSTEM (KOS)		

1. Description:

Some terminal numbers and connector symbols shown in the engine switch inspection procedures have been incorrect in the applicable Workshop Manuals. This Service Bulletin contains the corrected descriptions.

2. Applicable Manuals:

<EUR>

Manual	Pub. No.	Title (Info-ID)	Attached Sheet
2011 ASX Workshop Manual	CGWE11E2-CD (English) CGWF11E2-CD (French) CGWG11E2-CD (German) CGWS11E2-CD (Spanish) CGWI11E2-CD (Italian)	Engine Switch Inspection (M429-62-570-01800-01)	Attached sheet 2

<RUSSIA>

Underneath Manual	Underneath Pub. No.	Title (Info-ID)	Attached Sheet
2011 ASX Workshop Manual	N/A	Engine Switch Inspection (M429-62-570-01800-01)	Attached sheet 2

There may be some attached sheets not included in this Service Bulletin because they are not applicable to your market. Their sheet numbers are not listed in the above table.


3. Corrected Specifications:

See Attached sheet 2.

ENGINE SWITCH

REMOVAL AND INSTALLATION


M1429625600011




Removal steps
1. Combination meter bezel
2. Engine switch

INSPECTION

M1429625700018





ELECTRIC STEERING LOCK

REMOVAL AND INSTALLATION

M1429628100015

⚠ CAUTION

When the electric steering lock is replaced, be sure to complete the registration of chassis number.(Refer to P.42B-103.)

Refer to GROUP 37 – Disassembly and Assembly of Steering Shaft P.37-47.