# SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

| | | |
|---|---|---|
| PURPOSE : INFORMATION | ISSUE NO. : MSB-11E34-003B | DATE : 2015-05-25 |
| SUBJECT : SHOCK ABSORBER ASSEMBLY INSTALLATION | | <MODEL> <M/Y> |
| GROUP : REAR SUSPENSION | | (EUR/RUSSIA)<br>See following<br>2. Applicable Manuals table. |

## 1. Description:

To improve driving stability of the vehicle, the installation procedure for the RH shock absorber assembly has been changed in the applicable Workshop Manuals. This Service Bulletin contains the new procedure.

## 2. Applicable Manuals:

See Attached sheets 1 (1/2) and 1 (2/2).

## 3. Effective Date:

~~From the end of August 2010~~

## 4. Details:

~~New:~~
~~Install the shock absorber assembly (LH) so that the coil spring end faces the rear of the vehicle.~~
~~Install the shock absorber assembly (RH) so that the coil spring end faces the front of the vehicle.~~

~~Old:~~
~~Install the shock absorber assembly so that the coil spring end faces the rear of the vehicle.~~

By our confirmation, we found out that there is no need in the main point of the installation direction of the coil spring end in the shock absorber assembly.(LH/RH)

※MSB-11E34-003 was issued on Dec 5, 2011
※MSB-11E34-003A was not issued.
※MSB-11E34-003B was issued on May 25, 2015(This time)

Attached sheet 1 (1/2)

<EUR>

| Manual/Model | <M/Y> | Pub. No. | Title (Info-ID) |
|---|---|---|---|
| 2010 LANCER<br>Workshop Manual CD-ROM<br>(CY0A) | 10 | CG1E10E1-CD<br>(English)<br>CG1S10E1-CD<br>(Spanish)<br>CG1F10E1-CD<br>(French)<br>CG1G10E1-CD<br>(German)<br>CG1I10E1-CD<br>(Italian) | Shock Absorber Assembly Removal and Installation<br>(M341-00-250-65801-01) |
| 2010 LANCER SPORT BACK<br>Workshop Manual<br>CD-ROM<br>(CX0A) | | CG4E10E1-CD<br>(English)<br>CG4S10E1-CD<br>(Spanish)<br>CG4F10E1-CD<br>(French)<br>CG4G10E1-CD<br>(German)<br>CG4I10E1-CD<br>(Italian) | Shock Absorber Assembly Removal and Installation<br>(M341-00-250-74400-01) |
| 2011 LANCER<br>Workshop Manual CD-ROM<br>(CY0A) | 11 | CG1E11E1-CD<br>(English)<br>CG1S11E1-CD<br>(Spanish)<br>CG1F11E1-CD<br>(French)<br>CG1G11E1-CD<br>(German)<br>CG1I11E1-CD<br>(Italian) | Shock Absorber Assembly Removal and Installation<br>(M341-00-250-65801-01) |
| 2012 LANCER/<br>LANCER SPORTBACK<br>Workshop Manual CD-ROM<br>(CY0A/CX0A) | 12 | CG1E12E1-CD<br>(English)<br>CG1S12E1-CD<br>(Spanish)<br>CG1F12E1-CD<br>(French)<br>CG1G12E1-CD<br>(German)<br>CG1I12E1-CD<br>(Italian) | |
| 2011 ASX<br>Workshop Manual CD-ROM<br>(GA0W) | 11 | CGWE11E2-CD<br>(English)<br>CGWS11E2-CD<br>(Spanish)<br>CGWF11E2-CD<br>(French)<br>CGWG11E2-CD<br>(German)<br>CGWI11E2-CD<br>(Italian) | 2010 OUTLANDER<br>See Service Bulletin “SHOCK ABSORBER ASSEMBLY INSTALLATION” (11CD004). |

<RUSSIA>

| Underneath Manual/Model | <M/Y> | Underneath Pub. No. | Title (Info-ID) |
|---|---|---|---|
| 2010 LANCER Workshop Manual (CY0A) | 10 | N/A | Shock Absorber Assembly Removal and Installation (M341-00-250-65801-01) |
| 2010 LANCER SPORTBACK Workshop Manual (CX0A) | | N/A | Shock Absorber Assembly Removal and Installation (M341-00-250-74400-01) |
| 2011 LANCER Workshop Manual (CY0A) | 11 | N/A | Shock Absorber Assembly Removal and Installation (M341-00-250-65801-01) |
| 2012 LANCER/ LANCER SPORTBACK Workshop Manual (CY0A/CX0A) | 12 | N/A | |
| 2011 ASX Workshop Manual (GA0W) | 11 | N/A | 2010 OUTLANDER See Service Bulletin “SHOCK ABSORBER ASSEMBLY INSTALLATION” (11CD004). |