MITSUBISHI MOTORS

SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-13EM00-001	DATE : 2013-09-27
SUBJECT : UNDERCOAT APPLICATION LOCATIONS		<Affected Destination/Model> (MMNA/USTP/RUSSIA) <M/Y> 11
GROUP : GENERAL(Gr:00)		OUTLANDER SPORT/ASX(GA0W)

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual.

2. Affected service manuals :

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 OUTLANDER SPORT Service Manual	MSCD-017B-2011	UNDERCOAT APPLICATION LOCATIONS (M040-00-301-56800-01)	Attached sheet 1
2011 ASX Workshop Manual	CGWE11E2-CD (ENG) CGWF11E2-CD (FRE) CGWG11E2-CD (GER) CGWS11E2-CD (SPA) CGWI11E2-CD (ITA) RUSSIA:N/A	UNDERCOAT APPLICATION LOCATIONS (M040-00-301-53500-01)	Attached sheet 2

3. About the details :


Please refer to the attached document (Attached sheet 1-2)

4. Effective time : From the vehicle produced in the end of July, 2013 (Only for the vehicle produced in MMNA)

5. Affected EO : EO QD1188

UNDERCOAT APPLICATION LOCATIONS

- The under parts of the body is undercoated for anti-corrosive, anti-rust, anti-chipping, and anti-vibration performance.
- After correcting the body, restore as shown in the instructions of the figure, if necessary.
- Tape the areas marked with an asterisks to protect those areas from getting any undercoating on those areas.



NOTE:
: Undercoat [Film thickness is at least 1.0 mm (0.039 inch).]


ABD00294AB

TSB Revision

UNDERCOAT APPLICATION LOCATIONS

- The under parts of the body is undercoated for anti-corrosive, anti-rust, anti-chipping, and anti-vibration performance.
- After correcting the body, restore as shown in the instructions of the figure, if necessary.
- Tape the areas marked with an asterisks to protect those areas from getting any undercoating on those areas.

VEHICLES FOR RUSSIA



NOTE:
: Undercoat (Film thickness is at least 1.0 mm.)

ABD00294AC