SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-14E00-002	DATE : 2014-03-25
SUBJECT : INFORMATION ON 2015 PAJERO BODY REPAIR MANUAL		<DESTINATION/MODEL> (EUR) PAJERO(V80/90) <M/Y> 15
GROUP : GENERAL		

1. Description :

This Service Bulletin contains the information about the 2015 PAJERO BODY REPAIR MANUAL

2. Affected service manuals :

Applicable manual	Pub. No.	Content
2009.5 PAJERO (V80/V90) Workshop Manual (Body Repair Manual)	CBKE09E2-CD CBKF09E2-CD CBKG09E2-CD CBKS09E2-CD CBKI09E2-CD	Attached sheet

3. About the details :

Please refer to the attached document (Attached sheet)

4. Effective time : From 15MY vehicles.

GROUP 6

BODY COLOUR

CONTENTS

GENERAL INFORMATION 6-2

BODY COLOURING 6-2

BUMPER 6-2

LICENCE PLATE GARNISH <OPTIONAL> 6-3

GENERAL INFORMATION

M4060000201275

OUTLINE OF CHANGE


The sections body colouring of "FRONT BUMPER" and "LICENCE PLATE GARNISH" have been changed.

BODY COLOURING

BUMPER

M4060008000539


FRONT BUMPER



	Vehicles with radiator grille (plating)	Vehicles without radiator grille (plating)
1	Body colour <Except for A31> Silver (CMA10019) <A31>	Body colour <Except for A31> Silver (CMA10019) <A31>
2	Material colour	Material colour
3	Dark grey (CMH18048)	Black (CMX18006)
4	Silver (AC11169)	Material colour

LICENCE PLATE GARNISH <OPTIONAL>

M4060000700136



	A31	Except for A31
1	Black (AC10790)	Black (AC10790)
2	Silver (CMA10019)	Body colour
3	Material colour	Material colour