SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-14EXML51-002	DATE : 2014-02-27
SUBJECT : CHANGE OF THE NUMBER OF RIVETS IN THE FRONT BUMPER REINFORCEMENT B		<DESTINATION/MODEL> (AS PER ATTACHED 1) ASX/RVR(GA0W) <M/Y> 13-14
GROUP : EXTERIOR		

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual.(The number of the rivets in the front bumper reinforcement B is changed from 6 pieces to 4pieces)

2. Affected service manuals :

Please refer to the attached document (Attached sheet 1)

3. About the details :

Please refer to the attached document (Attached sheet 2)


4. Effective time : From the vehicle produced from early February in 2014

For overseas market Attached sheet 1

Destination	Applicable manual	Pub No.	Applicable title (INFO ID)	Content
MMNA/MEXICO	2013 Outlander Sport Service manual	MSCD-017B-2013 MEXICO:DRAFT	FRONT BUMPER ASSEMBLY DISASSEMBLY AND ASSEMBLY (M511-00-162-67100-01)	Attached sheet 2
	2014 Outlander Sport Service manual	MSCD-017B-2014 MEXICO:DRAFT		
KOREA	2013 RVR Workshop manual	DRAFT	FRONT BUMPER ASSEMBLY DISASSEMBLY AND ASSEMBLY (M511-00-162-70100-01)	
EU/RUSSIA/ SOUTH AFRICA	2013 ASX Workshop manual	CGAE13E2-CD (ENG) CGAF13E2-CD (FRE) CGAG13E2-CD (GER) CGAS13E2-CD (SPA) CGAI13E2-CD (ITA) RUSSIA:N/A	FRONT BUMPER ASSEMBLY DISASSEMBLY AND ASSEMBLY (M511-00-162-66000-01)	
	2014 ASX Workshop manual	CGAE14E1-CD (ENG) CGAF14E1-CD (FRE) CGAG14E1-CD (GER) CGAS14E1-CD (SPA) CGAI14E1-CD (ITA) RUSSIA:N/A		
	2015 ASX Workshop manual	CGAE15E1-CD (ENG) CGAF15E1-CD (FRE) CGAG15E1-CD (GER) CGAS15E1-CD (SPA) CGAI15E1-CD (ITA) RUSSIA:N/A	FRONT BUMPER ASSEMBLY DISASSEMBLY AND ASSEMBLY (M511-00-162-87500-01)	
G.EXP/GCC/ MMAL/NZ	2013 ASX/OUTLANDER SPORT Workshop manual	PWPE1204R (ENG) PWPS1205R (SPA) MMAL:AU900409 NZ:DRAFT	FRONT BUMPER ASSEMBLY DISASSEMBLY AND ASSEMBLY (M511-00-162-65900-01)	


Attached sheet 2

<国内>



フロントバンパーリーンホースメントBの取付けリベットの数を６個から４個に変更した。

<For overseas market>



The number of the rivets, which secure front bumper reinforcement B to the body, has been decreased from six to four.