SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-15E42-004	DATE : 2015-06-25
SUBJECT : Omission of the silencer application locations		<DESTINATION/MODEL> (EU/RUSSIA) <M/Y> 16
GROUP : Gr:42(Body)		OUTLANDER(GF0W)/ OUTLANDER PHEV(GG0W)

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual.

2. Affected service manuals :

Applicable manual	Pub. No.	Applicable title (INFO-ID)
2016 OUTLANDER/OUTLANDER PHEV Body Repair Manual	MSB-15E42-003	Added below "BODY CONSTRUCTION CHARACTERISTICS-UNDER BODY" (M010-01-401-82600-01)

3. About the details

Please refer to the attached document (Attached sheet)

<Added>

Attached sheet

SILENCER APPLICATION LOCATIONS

M4010000100292

An additional silencer (spray-type anti-vibration agent) is applied as shown, thus suppressing vibration and noise.

<LH Drive vehicles>



<RH Drive vehicles>



NOTE:
: 2.5 mm film thick spray-type anti-vibration agent. (Place two 1.6 mm melting sheet one on top of another.)

ABF00323AB