SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-15E51-001	DATE : 2015-03-02
SUBJECT : Leakage of the description regarding the maintenance procedure of the outside mirror inspection		<DESTINATION/MODEL> EU/RUSSIA <M/Y> 15
GROUP : Gr:51(Exterior)		PAJERO/MONTERO(V80/90)

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual.

2. Affected service manuals :

Applicable manual	Pub. No.	Applicable title (INFO ID)
2015 PAJERO/MONTERO Workshop Manual	CVWE15E1-CD (ENG) CVWF15E1-CD (FRE) CVWG15E1-CD (GER) CVWS15E1-CD (SPA) CVWI15E1-CD (ITA) RUSSIA:N/A	OUTSIDE MIRROR INSPECTION (M511-01-912-03500-01) <after>

3. About the details :

Please refer to the attached document (Attached sheet)

<Added>

Attached sheet

SIDE UNDER MIRROR
REMOVAL AND INSTALLATION



Removal steps

1. Side under mirror