SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-14EXML11-502	DATE : 2014-02-11
SUBJECT : LIQUID GASKET APPLICATION PROCEDURE		<DESTINATION/MODEL> MMNA/USTP/EUR/RUSSIA/ G.EXP/GCC/MMAL/NZ) <M/Y> ALL
GROUP : ENGINE(Gr:11)		Vehicles with 4G63 DOHC T/C

1. Description :

Please refer to the attached document for the correction of the error in writing existing in the applicable service manual. (Unnecessary portion of the liquid gasket application, which was mentioned in the affected workshop manuals, is erased)


2. Affected models :

MODEL		INFO-ID	MMNA/ USTP	EUR/ RUSSIA	G.EXP/ GCC	MMAL/ NZ
LANCER EVO	CZ4A	—	○	○	○	○
ECLIPSE	D30A	—	○	—	—	—
AIRTREK	CU0W	M113-00-190-33900-01	—	—	—	—
		M113-00-190-86700-01	—	○	—	—
		M113-00-190-49200-01	—	—	○	○

○ : Applicable

3. About the details :

<Correct>



<Incorrect>

