SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-15E42-002	DATE : 2015-02-16
SUBJECT : Information on 2015.5MY ASX BODY REPAIR MANUAL		<DESTINATION/MODEL> (EUR) ASX(GA0W) <M/Y> 15.5
GROUP : Gr:42(Body)		

1. Description :

This Service Bulletin contains the information about the 2015.5 ASX body repair manual.

2. Affected service manuals :

Applicable manual	Pub. No.
2015 ASX Workshop Manual	CGAE15E1-CD (Eng) CGAF15E1-CD (Fre) CGAG15E1-CD (Ger) CGAS15E1-CD (Spa) CGAI15E1-CD (Ita)

3. About the details :

Please refer to the attached document (Attached sheet)

4. Effective time : From the vehicles of 15.5MY

GROUP 1

BODY CONSTRUCTION

CONTENTS

GENERAL INFORMATION 1-2

BODY CONSTRUCTION CHARACTERISTICS 1-2

FRONT BODY 1-2

UNDER BODY 1-3

GENERAL INFORMATION

M4010000200891

OUTLINE OF CHANGE

The sections "FRONT BODY" and "UNDER BODY" have been revised as 9HD engine has been introduced.

BODY CONSTRUCTION CHARACTERISTICS


FRONT BODY

M4010010001868

FRONT SIDEMEMBER REINFORCEMENT <9HD>

The following components have been changed.

<Left side>



NOTE :
: Indicate the same parts as for previous models.


ABE00713AB

UNDER BODY

M4010014001815

FRONT FLOOR <9HD>

The following components have been changed.




NOTE :
: Indicate the same parts as for previous models.

ABE00714AB

REAR FLOOR SIDEMEMBER REINFORCEMENT <9HD>

The following components have been added or discontinued.



NOTE :
: Indicate the same parts as for previous models.

ABE00715AB

NOTES