SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-15E42-005	DATE : 2015-09-01
SUBJECT : INFORMATION ON 2016 LANCER/LANCER SPORTBACK BODY REPAIR MANUAL		<DESTINATION/MODEL> (EU/RUSSIA) <M/Y> 16
GROUP : Gr.42(Body)		LANCER(CY0A)/LANCER SPORTBACK(CX0A)

1. Description :

This Service Bulletin contains the information about 2016 LANCER and LANCER SPORTBACK Body repair manual. The point to be changed in 16MY is Gr:6 (Body colour)

2. Affected service manuals :

Applicable service manual is “2015 LANCER/LANCER SPORTBACK Workshop manual” which was published by the service bulletin “MSB-14E00-003(14CD027) in April 2014.

3. About the details :

Please refer to the attached document (Attached sheet)

4. Effective time : From the vehicles of 16MY.

GROUP 6

BODY COLOUR

CONTENTS

GENERAL INFORMATION 6-2
BODY COLOUR CHARTS 6-2

GENERAL INFORMATION

M4060000201286

OUTLINE OF CHANGE

The section "BODY COLOUR CHARTS" has been changed.

BODY COLOUR CHARTS

M4060002004685

Check the vehicle's body colour code, and then use this body colour chart to determine the refinishing paint supplier from which the colour can be purchased.

Colour	Colour code	Colour number	Colour name	Coating film structure	Composition of film
BLUE	D06	CMD10006	Lightning Blue Mica	2P	Interferenced Pearl
RED	P26	CMP10026	Red Metallic	2M	Metallic
GREY	U17	CMU10017	Titanium Grey Metallic	2M	Metallic
SILVER	U25	CSU10025	Sterling Silver Metallic	2M	Metallic
WHITE	W13	CMW10013	White Pearl	3P	Pearl
WHITE	W37	CMW10037	White Solid	2S	Solid
BLACK	X42	AC11342	Black Mica	2P	Interferenced Pearl

NOTE:

- *The coating film structure indicates top coating only (2S: 2 coat solid, 2M: 2 coat metallic, 2P: 2 coat pearl, 3P: 3 coat pearl).*
- *For painting, inner panel colours should be similar to the outer panel colours.*