SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-15EXL42-003	DATE : 2015-07-13
SUBJECT : Change of mention about the number of times to sound of the warning buzzer at the time of the electric tailgate operation		<DESTINATION/MODEL> (As per attached sheet 1) <M/Y> 16
GROUP : Gr:42(Body)		OUTLANDER(GF0W)/

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual.

2. Affected service manuals :

Please refer to the attached document (Attached sheet 1)

3. About the details :

Please refer to the attached document (Attached sheet 2-5)

4. Effective time : From the vehicles produced in the early of May 2015.

Attached sheet 1

RUSSIA,/ARGENTINA,/SOUTH AFRICA

Applicable manual	Pub. No.	Applicable title(Info-ID)	Content
2016 OUTLANDER Workshop Manual	N/A (RUSSIA) DRAFT (ARGENTINA, SOUTH AFRICA)	Added above “SERVICE SPECIFICATION” (M424-00-030-07200-01)	Attached sheet 2

G.EXP/GCC

Applicable manual	Pub. No.	Applicable title(Info-ID)	Content
2016 OUTLANDER Workshop Manual	PWRE1504R (ENGLISH) PWRS1505R (SPANISH)	GENERAL INFORMATION (M421-00-011-63000-01)	Attached sheet 3

MMAL /NZ

Applicable manual	Pub. No.	Applicable title(Info-ID)	Content
2016 OUTLANDER Workshop Manual	AU900424 (MMAL), DRAFT (NZ)	GENERAL INFORMATION (M421-00-011-66300-01)	Attached sheet 4

RUSSIA KD

Applicable manual	Pub. No.	Applicable title(Info-ID)	Content
2016 OUTLANDER Workshop Manual	N/A	GENERAL INFORMATION (M421-00-011-65200-01)	Attached sheet 5

Attached sheet 2

<Added>

GENERAL INFORMATION

Now the warning buzzer will sound once instead of four times (during opening) or three times (during closing).

Attached sheet 3

GENERAL INFORMATION

OUTLINE OF CHANGE

Due to the following change, the service procedure has been established.

- Fender reshaped
- Fender protector rear discontinued <Added>
- Front pillar pad B, C added
- Front splash shield mounting tapping screw discontinued
- Due to the addition of the lane departure warning system (LDW), the windshield service procedure has been changed.
- The grease application locations have been changed due to the changed sunroof deflector.
- Upper frame-to-front pillar brace added
- Now the warning buzzer will sound once instead of four times (during opening) or three times (during closing).

Attached sheet 4

GENERAL INFORMATION

OUTLINE OF CHANGE

Due to the following change, the service procedure has been established. <Added>

- Fender reshaped
- Fender protector rear discontinued
- Front pillar pad B, C added
- The grease application locations have been changed due to the changed sunroof deflector.
- Upper frame-to-front pillar brace added
- Now the warning buzzer will sound once instead of four times (during opening) or three times (during closing).

Attached sheet 5

GENERAL INFORMATION

OUTLINE OF CHANGE

Due to the following change, the service procedure has been established.

- Fender reshaped
- Fender protector rear discontinued
- Front pillar pad A, B, C added

<Added>

- Front splash shield mounting tapping screw discontinued
- A heated windshield is available as an optional equipment.
- The grease application locations have been changed due to the changed sunroof deflector.
- Upper frame to front pillar brace added
- Now the warning buzzer will sound once instead of four times (during opening) or three times (during closing).