SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-15EXL51-001	DATE : 2015-02-05
SUBJECT : Change of the double-sided tape affixed location in the front and rear door garnish		<DESTINATION/MODEL> (as shown below) <M/Y> 16
GROUP : Gr:51(Exterior)		Outlander(GF0W)

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual.

2. Affected service manuals :

<EU/RUSSIA/SOUTH AFRICA/ARGENTINA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)
2016 OUTLANDER/ OUTLANDER PHEV Workshop Manual CD-ROM	CGFE16E1-CD (ENG) CGFF16E1-CD (FRE) CGFG16E1-CD (GER) CGFS16E1-CD (SPA) CGFI16E1-CD (ITA) RUSSIA:N/A S.AFRICA/ARGENTINA: DRAFT	GARNISH REMOVAL AND INSTALLATION (M511-00-411-20700-01)

<RUSSIA KD>

Applicable manual	Pub. No.	Applicable title (INFO-ID)
2016 OUTLANDER Workshop Manual CD-ROM	N/A	GARNISH REMOVAL AND INSTALLATION (M511-00-411-18800-01)

<MMAL/NZ>

Applicable manual	Pub. No.	Applicable title (INFO-ID)
2016 OUTLANDER/ OUTLANDER Workshop Manual CD-ROM	MMAL:AU900424 NZ:DRAFT	GARNISH REMOVAL AND INSTALLATION (M511-00-411-18800-01)

<G.EXP/GCC/Brazil>

Applicable manual	Pub. No.	Applicable title (INFO-ID)
2016 OUTLANDER/ OUTLANDER Workshop Manual CD-ROM	PWRE1504R((ENG) PWRS1505R(SPA)	GARNISH REMOVAL AND INSTALLATION (M511-00-411-18800-01)

3. About the details :


Please refer to the attached document (Attached sheet)

4. Effective time : From 16MY of the related vehicles

GARNISHES


REMOVAL AND INSTALLATION

M1511004101188




ACE04189AB

<old>



ACE03227AB

<New>



ACE04188AB

Removal steps

1. Front door garnish
2. Rear door garnish