SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-15EXML51-501	DATE : 2015-12-01
SUBJECT : Error in writing of the adjustment of the jet type washer nozzle injection position		<DESTINATION/MODEL> As per attached sheet 1 <M/Y> 13-16
GROUP : Gr:51(Exterior)		OUTLANDER(GF0W)/ OUTLANDER PHEV(GG0W)

1. Description :

Please refer to the attached document for the correction of the error in writing existing in the applicable service manual.

2. Affected service manuals :

Please refer to the attached document (Attached sheet 1)

3. About the details :

Please refer to the attached document (Attached sheets 3-4)

Attached sheet 1

For overseas market

EU/RUSSIA/ARGENTINA/SOUTH AFRICA

Applicable manual	Pub. No.	Applicable title (Info-ID)	Contents
2013 OUTLANDER Workshop Manual	CGFE13E1-CD (English) CGFF13E1-CD (French) CGFG13E1-CD (German) CGFS13E1-CD (Spanish) CGFI13E1-CD (Italian) N/A (RUSSIA)	INSPECTION (M511-01-913-72600-01)	Attached sheet 3
2014 OUTLANDER/ OUTLANDER PHEV Workshop Manual	CGFE14E2-CD (English) CGFF14E2-CD (French) CGFG14E2-CD (German) CGFS14E2-CD (Spanish) CGFI14E2-CD (Italian) N/A (RUSSIA) DRAFT (ARGENTINA, SOUTH AFRICA)	INSPECTION (M511-01-913-87800-01)	Attached sheet 3
2014.5 OUTLANDER/ OUTLANDER PHEV Workshop Manual	CGFE14E3-CD (English) CGFF14E3-CD (French) CGFG14E3-CD (German) CGFS14E3-CD (Spanish) CGFI14E3-CD (Italian) DRAFT (ARGENTINA, SOUTH AFRICA)	INSPECTION (M511-01-913-87800-01)	Attached sheet 3
2016 OUTLANDER/ OUTLANDER PHEV Workshop Manual	CGFE16E1-CD (English) CGFF16E1-CD (French) CGFG16E1-CD (German) CGFS16E1-CD (Spanish) CGFI16E1-CD (Italian) N/A (RUSSIA) DRAFT (ARGENTINA, SOUTH AFRICA)	INSPECTION (M511-01-913-87800-01)	Attached sheet 3

Attached sheet 1

AUSTRALIA/NEW ZEALAND/CHINA

Applicable manual	Pub. No.	Applicable title (Info-ID)	Contents
2013 OUTLANDER Workshop Manual	AU900304 (MMAL) DRAFT (NZ, CHINA)	INSPECTION (M511-01-913-72600-01)	Attached sheet 3
2016 OUTLANDER PHEV Workshop Manual	AU900504 (MMAL), DRAFT (NZ)	INSPECTION (M511-01-914-00800-01)	Attached sheet 3

GENERAL EXPORT/GCC/BRAZIL

Applicable manual	Pub. No.	Applicable title (Info-ID)	Contents
2014 OUTLANDER Workshop Manual	PWRE1303R (English) PWRS1304R (Spanish)	INSPECTION (M511-01-913-90800-01)	Attached sheet 3

MMNA/MEXICO


Applicable manual	Pub. No.	Applicable title (Info-ID)	Contents
2014 OUTLANDER Workshop Manual	MSCD-007B-2014 (MMNA)	INSPECTION (M511-01-913-72600-01)	Attached sheet 4
2015 OUTLANDER Workshop Manual	MSCD-007B-2015 (MMNA)	INSPECTION (M511-01-913-72600-01)	Attached sheet 4
2016 OUTLANDER Workshop Manual	MSCD-007B-2016- (MMNA) DRAFT (MEXICO)	INSPECTION (M511-01-913-72600-01)	Attached sheet 4

Attached sheet 3

WINDSHIELD WASHER FLUID EJECTION CHECK

Adjustment of the jet type washer nozzle injection position

Unit: mm



ACC00351AD

<Incorrect>

~~Replace the washer nozzle if it does not spray washer fluid onto the shown area.~~

<Correct>

1. Check whether washer fluid is sprayed as shown.

⚠ CAUTION

Be careful not to break a pin inside the washer nozzle when you adjust it.


2. If the spray pattern shown is not satisfied, use a pin (thinner than 0.7 mm in diameter) to adjust the washer nozzle.

Attached sheet 4

WINDSHIELD WASHER FLUID EJECTION CHECK

Adjustment of the jet type washer nozzle injection position

Unit: mm (in)



ACC00351AD

<Incorrect>

~~Replace the washer nozzle if it does not spray washer fluid onto the shown area.~~

<Correct>

1. Check whether washer fluid is sprayed as shown.

⚠ CAUTION

Be careful not to break a pin inside the washer nozzle when you adjust it.

2. If the spray pattern shown is not satisfied, use a pin [thinner than 0.7 mm (0.03 in) in diameter] to adjust the washer nozzle.