SERVICE BULLETIN

MITSUBISHI MOTORS

DOMESTIC SALES & AFTER SALES SERVICE OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-11E11-006	DATE : 2011-11-20
SUBJECT : ID MARK ON CONNECTING ROD AND CRANKSHAFT BEARINGS FOR 3A9 AND 4A9 ENGINES		<MODEL> (EUR) Vehicles equipped with 3A9 or 4A9 engine / <M/Y> ALL
GROUP : ENGINE		

1. Description:

To improve productivity, the identification marking on connecting rod bearings and crankshaft bearings for 3A9 and 4A9 engines are changed from a paint color code to a stamped number. This Service Bulletin contains the comparison charts of the new and old coding systems.

2. Interchangeability:

Interchangeable.

3. Effective Date:

From the vehicles produced in September 2011

4. Details:

The identification marking is changed from a paint color code to a stamped number. The location of the mark is also changed.

Connecting rod bearing	
New (stamped number)	Old (color code)
1	Blue
2	Black
3	Red



Upper crankshaft bearing	
New (stamped number)	Old (color code)
1	Green
2	Black
3	Red

Lower crankshaft bearing	
New (stamped number)	Old (color code)
1	Green
2	Black
3	Red
4	White
5	Purple