SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-11E34-001	DATE : 2011-06-20
SUBJECT : SHOCK ABSORBER ASSEMBLY INSTALLATION		<MODEL> (EUR/RUSSIA) OUTLANDER (CW0W) <M/Y> 10–11
GROUP : REAR SUSPENSION		

1. Description:

In order to improve the position of the spring, the installation procedure for the RH shock absorber assembly has been changed in the applicable Workshop Manuals. This Service Bulletin contains the modified description.

2. Applicable Manuals:

<EUR>

Manual	Pub. No.	Title (Info-ID)
2010 OUTLANDER Workshop Manual CD-ROM	CGXE10E1-CD (English) CGXS10E1-CD (Spanish) CGXF10E1-CD (French) CGXG10E1-CD (German) CGXI10E1-CD (Italian)	Shock Absorber Assembly Removal and Installation (M341-00-250-85200-01)
2011 OUTLANDER Workshop Manual CD-ROM	CGXE11E1-CD (English) CGXS11E1-CD (Spanish) CGXF11E1-CD (French) CGXG11E1-CD (German) CGXI11E1-CD (Italian)	Shock Absorber Assembly Removal and Installation (M341-00-250-85201-01)

<RUSSIA>

Underneath Manual	Underneath Pub. No.	Title (Info-ID)
2010 OUTLANDER Workshop Manual	N/A	Shock Absorber Assembly Removal and Installation (M341-00-250-85200-01)
2011 OUTLANDER Workshop Manual	N/A	Shock Absorber Assembly Removal and Installation (M341-00-250-85201-01)

3. Effective Date:

From late July 2010

4. Details:

<New>

- Install the shock absorber assembly (LH) so that the coil spring end faces the rear of the vehicle.
- Install the shock absorber assembly (RH) so that the coil spring end faces the front of the vehicle.

<Old>

- Install the shock absorber assembly so that the coil spring end faces the rear of the vehicle.