MITSUBISHI MOTORS

SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-11E34-003	DATE : 2012-01-20
SUBJECT : SHOCK ABSORBER ASSEMBLY INSTALLATION		<MODEL> <M/Y>
GROUP : REAR SUSPENSION		(EUR/RUSSIA) See following 2. Applicable Manuals table.

1. Description:

To improve driving stability of the vehicle, the installation procedure for the RH shock absorber assembly has been changed in the applicable Workshop Manuals. This Service Bulletin contains the new procedure.

2. Applicable Manuals:

See Attached sheets 1 (1/2) and 1 (2/2).

3. Effective Date:

From the end of August 2010

4. Details:

New:
Install the shock absorber assembly (LH) so that the coil spring end faces the rear of the vehicle.
Install the shock absorber assembly (RH) so that the coil spring end faces the front of the vehicle.

Old:
Install the shock absorber assembly so that the coil spring end faces the rear of the vehicle.

Attached sheet 1 (1/2)

<EUR>

Manual/Model	<M/Y>	Pub. No.	Title (Info-ID)
2010 LANCER Workshop Manual CD-ROM (CY0A)	10	CG1E10E1-CD (English) CG1S10E1-CD (Spanish) CG1F10E1-CD (French) CG1G10E1-CD (German) CG1I10E1-CD (Italian)	Shock Absorber Assembly Removal and Installation (M341-00-250-65801-01)
2010 LANCER SPORT BACK Workshop Manual CD-ROM (CX0A)		CG4E10E1-CD (English) CG4S10E1-CD (Spanish) CG4F10E1-CD (French) CG4G10E1-CD (German) CG4I10E1-CD (Italian)	Shock Absorber Assembly Removal and Installation (M341-00-250-74400-01)
2011 LANCER Workshop Manual CD-ROM (CY0A)	11	CG1E11E1-CD (English) CG1S11E1-CD (Spanish) CG1F11E1-CD (French) CG1G11E1-CD (German) CG1I11E1-CD (Italian)	Shock Absorber Assembly Removal and Installation (M341-00-250-65801-01)
2012 LANCER/ LANCER SPORTBACK Workshop Manual CD-ROM (CY0A/CX0A)	12	CG1E12E1-CD (English) CG1S12E1-CD (Spanish) CG1F12E1-CD (French) CG1G12E1-CD (German) CG1I12E1-CD (Italian)	
2011 ASX Workshop Manual CD-ROM (GA0W)	11	CGWE11E2-CD (English) CGWS11E2-CD (Spanish) CGWF11E2-CD (French) CGWG11E2-CD (German) CGWI11E2-CD (Italian)	2010 OUTLANDER See Service Bulletin “SHOCK ABSORBER ASSEMBLY INSTALLATION” (11CD004).

<RUSSIA>

Underneath Manual/Model	<M/Y>	Underneath Pub. No.	Title (Info-ID)
2010 LANCER Workshop Manual (CY0A)	10	N/A	Shock Absorber Assembly Removal and Installation (M341-00-250-65801-01)
2010 LANCER SPORTBACK Workshop Manual (CX0A)		N/A	Shock Absorber Assembly Removal and Installation (M341-00-250-74400-01)
2011 LANCER Workshop Manual (CY0A)	11	N/A	Shock Absorber Assembly Removal and Installation (M341-00-250-65801-01)
2012 LANCER/ LANCER SPORTBACK Workshop Manual (CY0A/CX0A)	12	N/A	
2011 ASX Workshop Manual (GA0W)	11	N/A	2010 OUTLANDER See Service Bulletin “SHOCK ABSORBER ASSEMBLY INSTALLATION” (11CD004).