SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-12E00-001A	DATE : 2012-03-28
SUBJECT : INFORMATION ON 2012 PAJERO/MONTERO		<MODEL> (EUR/RUSSIA) <M/Y> 12
GROUP : GENERAL		PAJERO/MONTERO(V80/90)

1. Description:

This Service Bulletin contains the information about change of the maintenance points of installation bolt of the transmission mount insulator
<kind of the installation bolt>
Washer bolt(NEW) ← Flange bolt(OLD)
<Clamping torque>
52±6 N・m(NEW) ← 59±9 N・m(OLD)


2. Applicable manual

Destination	Applicable manual	Pub.No.	Applicable title(INFO ID)	Content
EUR/RUSSIA	2012 PAJERO/ MONTERO WORKSHOP MANUAL	CBKE12E1-CD (Eng) CBKS12E1-CD (Spa) CBKF12E1-CD (Fre) CBKG12E1-CD (Ger) CBKI12E1-CD (Ita) RUSSIA:N/A	TRANSMISSION REMOVAL AND INSTALLATION △A ~~M222-11-240-54101-01~~ M221-10-240-54101-01	Attached sheet 4
			TRANSMISSION REMOVAL AND INSTALLATION <V5A5A> M231-11-700-48701-01	Attached sheet 6
			TRANSMISSION REMOVAL AND INSTALLATION <V5AWF> M231-11-700-52802-01	Attached sheet 7


3.Details

See Attached sheet 4/6/7

Attached sheet 4 (1/2)




Attached sheet 4 (2/2)



Attached sheet 6

<V5A5A>



Attached sheet 7

<V5AWF>

