SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-13EXL22-001	DATE : 2013-04-01
SUBJECT : FRONT TRANSAXLE FLUID		<Destination/Model> (EUR/MMAL/NZ) <M/Y> 14
GROUP : TRANSAXLE		OUTLANDER/OUTLANDER PHEV(GF0W)

1. Description :

[EU/MMAL/NZ]

〈New〉 NOTE:

1. If the front transaxle assembly or the valve body assembly is replaced, refill the fluid and then install the filler plug with the gasket.

〈Old〉 NOTE:

1. If the valve body assembly is replaced, refill the fluid and then install the filler plug with the gasket.

2. Applicable service manual :

EUR

Applicable manual	Pub. No.	Applicable title (INFO ID)
2014 OUTLANDER/OUTLANDER PHEV Workshop Manual	CGFE14E1-CD (English) CGFF14E1-CD (French) CGFG14E1-CD (German) CGFS14E1-CD (Spanish) CGFI14E1-CD (Italian)	Gr.22D: TRANSAXLE FLUID CHANGE (M222-30-510-01800-01)

MMAL/NZ

Applicable manual	Pub. No.	Applicable title (INFO ID)
2014 OUTLANDER/OUTLANDER PHEV Workshop Manual	AU900408 (MMAL) DRAFT (NZ)	Gr.22C: TRANSAXLE FLUID CHANGE (M222-30-510-01800-01)

3. Details :

See the “Description” as above