SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-14E23-001	DATE : 2014-03-17
SUBJECT : A/T FLUID COOLER WITH BYPASS SYSTEM		<DESTINATION/MODEL> (EUR) L200(KA0T/KB0T) <M/Y> 15
GROUP : A/T(Gr:23A)		

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual. (The service procedure has been added due to the introduction of A/T fluid cooler with bypass system)

2. Affected service manuals :

Applicable manual	Applicable manual	Applicable title (INFO ID)	Content
2015 L200 Workshop Manual	CKTE15E1-CD(ENG) CKTF15E1-CD(FRE) CKTG15E1-CD(GER) CKTS15E1-CD(SPA) CKTI15E1-CD(ITA)	A/T FLUID COOLER REMOVAL AND INSTALLATION (M231-12-870-48000-01)	Attached Sheet

3. About the details :

Please refer to the attached document (Attached sheet)

GROUP 23A

AUTOMATIC TRANSMISSION

CONTENTS

GENERAL INFORMATION 23A-2
A/T FLUID COOLER. 23A-2
REMOVAL AND INSTALLATION 23A-2

GENERAL INFORMATION

M1231100100965

OUTLINE OF CHANGES


Due to the introduction of an A/T fluid cooler with bypass system, a service procedure has been added.

A/T FLUID COOLER

REMOVAL AND INSTALLATION

M1231128700491

Pre-removal and Post-installation Operation
- Front Bumper Removal and Installation.
- Front Exhaust Pipe Removal and Installation.
- Under Skid Plate and Engine Room Under Cover Removal and Installation.
- A/T Fluid Draining and Refilling.



Removal steps

1. Cooler hose
2. Gasket
3. Hose
4. A/T fluid cooler assembly
5. Pipe assembly
6. Return hose
7. Return pipe
8. Hose

Removal steps (Continued)

9. Feed hose
10. Cooler hose
11. Hose
12. Cooler hose
13. Orifice
14. Cooler pipe assembly
15. Cooler pipe assembly