SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-14E80_90-501	DATE : 2014-11-25
SUBJECT : Error in writing of the connector number in the quick charging control system		<DESTINATION/MODEL> (EUR) i-MiEV(HA3W) <M/Y> 15
GROUP : Gr:80/90		

1. Description :

Please refer to the attached document for the correction of the error in writing existing in the applicable service manual.

2. Affected service manuals :

Applicable manual	Pub. No.	Applicable title (INFO ID)	Content
2015 i-MiEV Workshop Manual CD-ROM	CHAE15E1-CD (Eng) CHAF15E1-CD (Fra) CHAG15E1-CD (Ger) CHAI15E1-CD (Ita) CHAS15E1-CD (Spa)	QUICK CHARGING CONTROL SYSTEM (M901-03-660-10800-01)	Attached sheet 4

3. About the details :

Please refer to the attached document (Attached sheet 4)

QUICK CHARGING CONTROL SYSTEM (CONTINUED)

