SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CHANGE	ISSUE NO. : MSB-15EXML11-001	DATE : 2015-09-01
SUBJECT : Setting of the special tool MB992922(Valve stem seal installer adjustable)		<DESTINATION/MODEL> (As shown below) <M/Y> ALL
GROUP : Gr:11(Engine)		

1. Description :

Please refer to the attached document for the information about the change of mention in the applicable service manual. The special tool MB992922(Valve stem seal installer adjustable), which includes MB992677(Valve seal installer adjustable) and MB992855(Guide pin 5.4), is newly set. By this change, the supply of MB992677 is stopped.

2. Affected models and destinations

This change is affected to the models of the following engines in all destinations.

- 3B2
- 3G8
- 3A9/4A9
- 4J1
- 4G9
- 4G6(S4)
- 6B3
- 6G7(S4)
- 6A1
- 4N1
- 4D5(D4)

3. About the details :


Please refer to the attached document (Attached sheet 2)

※Applicable maintenance contents

- Disassembly and installation of the valve stem seal (for engine mechanical)
- Disassembly and installation of the cylinder head valve (for engine overhaul)


<Old>

Valve stem seal installer
adjustable（MB992677）




1: Chuck
2: Sleeve
3: Lock nut (small)
4: Outer pipe
5: Lock nut (large)
6: Guide pin (5.9)
7: Guide pin (4.9)
8: Cap

Guide pin (5.4)
(MB992855)



<New>

Valve stem seal installer
adjustable（MB992922）



1: Chuck
2: Sleeve
3: Lock nut (small)
4: Outer pipe
5: Lock nut (large)
6: Guide pin (5.9)
7: Guide pin (4.9)
8: Cap
9: Guide pin (5.4)