MITSUBISHI MOTORS

SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-12E42-001B	DATE : 2012-06-12
SUBJECT : INFORMATION ABOUT THE CHANGE OF THE MAINTENANCE POINTS OF 2012 LANCER EVOLUTION		<MODEL> (EUR) <M/Y> 12
GROUP : BODY		LANCER EVOLUTION(CZ4A)

1. Description:

This Service Bulletin contains the information about change of the maintenance points of installation bolts of the front fender (The abolition of seven washers)

2. Applicable manual

Destination	Applicable manual	Pub.No.
EU	2012 LANCER EVOLUTION WORKSHOP MANUAL	CGEE10E1-CD(Eng) CGES10E1-CD(Spa) CGEF10E1-CD(Fre) CGEG10E1-CD(Ger) CGEI10E1-CD(Ita)


Applicable title (INFO ID)	Content
FENDER REMOVAL AND INSTALLATION ~~(M421-00-190-41300-01)~~ (M421-00-191-41300-01) △A	Attached sheet 2

3. Details

See Attached sheet 2

REMOVAL AND INSTALLATION

Pre-removal and post-installation operation
- Front splash shield removal and installation
- Side air dam removal and installation (Refer to GROUP 51 – Side Air Dams .)
- Front bumper side bracket removal and installation (Refer to GROUP 51 – Front Bumper Assembly, Radiator Grille .)
- Front delta garnish removal and installation (Refer to GROUP 51 – Garnish and Moulding .)
- Front deck garnish removal and installation (Refer to GROUP 51 – Windshield Wiper .)
- Headlamp assembly removal and installation (Refer to GROUP 54A – Headlamp .)
- Side turn-signal lamp removal and installation (Refer to GROUP 54A – Side Turn Signal Lamp .)



AC900040AB

Removal steps

<<A>> >>A<< 1. Fender
2. Fender protector rear

Removal steps

3. Front fender bracket
4. Front fender garnish

REMOVAL SERVICE POINT

<<A>> FENDER REMOVAL

1. Remove the fender protector rear assembling clip.