SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-13EXL37-501A	DATE : 2013-12-25
SUBJECT : STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION		<Affected Destination/Model> (As per attached 1) <M/Y> 07-15
GROUP : STEERING(Gr:37)		L200/L200 SPORTERO/TRITON/STRADA/STRADA SPORTERO(KA0T/KB0T)

1. Description :

Please refer to the attached document for the correction of the error in writing existing in the applicable service manual.

2. Affected service manuals :

Please refer to the attached document (Attached sheet 1)
(There are the errors in writing in the applicable service manuals of L200/L200 SPORTERO/TRITON/STRADA/STRADA SPORTERO regarding the steering column support bracket.)

3. About the details :

Please refer to the attached document (Attached sheet 2-6)

※ Original MSB(MSB-13EXL37-501) was issued on Oct 25, 2013
Revised A version(MSB-13EXL37-501A) was issued on Dec 25, 2013

FOR EU/RUSSIA

Applicable manual	Pub. No.	Applicable title (INFO ID)	Content
2010 L200 Workshop Manual	CCRE10E1-CD(ENG) CCRF10E1-CD(FRE) CCRG10E1-CD(GER) CCRS10E1-CD(SPA) CCRI10E1-CD(ITA)	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-43300-01）	Attached sheet 2
2011 L200 Workshop Manual	CCRE11E1-CD(ENG) CCRF11E1-CD(FRE) CCRG11E1-CD(GER) CCRS11E1-CD(SPA) CCRI11E1-CD(ITA)	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-43300-01）	Attached sheet 2
2012 L200 Workshop Manual	CCRE12E1-CD(ENG) CCRF12E1-CD(FRE) CCRG12E1-CD(GER) CCRS12E1-CD(SPA) CCRI12E1-CD(ITA)	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-43300-01）	Attached sheet 2
2013 L200 Workshop Manual	CKTE13E1-CD(ENG) CKTF13E1-CD(FRE) CKTG13E1-CD(GER) CKTS13E1-CD(SPA) CKTI13E1-CD(ITA)	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-48800-01）	Attached sheet 2
2014 L200 Workshop Manual	CKTE14E1-CD(ENG) CKTF14E1-CD(FRE) CKTG14E1-CD(GER) CKTS14E1-CD(SPA) CKTI14E1-CD(ITA)	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-48800-01）	Attached sheet 2
2015 L200 Workshop Manual	CKTE15E1-CD(ENG) CKTF15E1-CD(FRE) CKTG15E1-CD(GER) CKTS15E1-CD(SPA) CKTI15E1-CD(ITA)	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-48800-01）	Attached sheet 2


Except EU/RUSSIA(FOR G.EXP/GCC/MMAL/THAI/MEXICO/SOUTH AFRICA)

Applicable manual	Pub. No.	Applicable title (INFO ID)	Content
2007 L200/SPORTERO/ TRITON/STRADA Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE0603R1(ENG) PWTS0604R1(SPA) THAI:DRAFT MMAL:MR936105 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION (M372-00-310-23900-01)	Attached sheet 3
2008 L200/SPORTERO/ TRITON/STRADA Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE0703R(ENG) PWTS0704R(SPA) THAI:DRAFT MMAL:MR936232 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION (M372-00-310-28400-01)	Attached sheet 4
2009 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE0806R(ENG) PWTS0807R(SPA) THAI:DRAFT MMAL:MR936476 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION (M372-00-310-30300-01)	Attached sheet 5
2010 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE0903R(ENG) PWTS0904R(SPA) THAI:DRAFT MMAL:MR936949 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION (M372-00-310-30301-01)	Attached sheet 2
2011 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE1002R(ENG) PWTS1003R(SPA) THAI:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION (M372-00-310-30301-01)	Attached sheet 2

	MEXICO:DRAFT MMAL:AU900054		
2012 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE1105R(ENG) PWTS1106R(SPA) THAI:DRAFT MMAL:AU900212 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-30301-01）	Attached sheet 2
2013 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE1208R(ENG) PWTS1209R(SPA) THAI:DRAFT MMAL:AU900302 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-49900-01）	Attached sheet 2, 6 A
2014 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE1308R(ENG) PWTS1309R(SPA) THAI:DRAFT MMAL:AU900406 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-49900-01）	Attached sheet 2, 6 A
2015 L200/SPORTERO/ TRITON/STRADA/ STRADA SPORTERO Workshop Manual	G.EXP/GCC/SOUTH AFRICA : PWTE1308R(ENG) PWTS1309R(SPA) THAI:DRAFT MMAL:AU900413 MEXICO:DRAFT	STEERING COLUMN SHAFT ASSEMBLY REMOVAL AND INSTALLATION （M372-00-310-49900-01）	Attached sheet 2, 6 A

<LHD>

Attached sheet 2




<Correct>
<2WD (except High rider)>

<Correct>
<2WD (High rider), 4WD>

<Incorrect>
~~<2WD (High rider), 4WD>~~

<Incorrect>
~~<2WD (except High rider)>~~




Specified sealant:
3M ATD Part No.8513 or equivalent

AC511177AG


Attached sheet 3

<LH drive vehicles>



AC511177AD


<LH drive vehicles>



AC511177AE


<LHD>

Attached sheet 5



AC511177AF

A Attached sheet 6



AC511272 AF