SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : INFORMATION	ISSUE NO. : MSB-13EXL54-001	DATE : 2013-06-10
SUBJECT : ABOLITION OF CLIPS FOR INSTALLATION OF BREATHER HOSE		<Destination/Model> (EUR/MMAL/NZ) OUTLANDER PHEV <M/Y> 14
GROUP : POWER UNIT & BATTERY FOR DRIVE(Gr.54D)		

1. Description :

See the attached document for the information about the change of mention in the applicable service manual.

2. Applicable service manual :

Manual	Pub. No.	Applicable title (Info-ID)
2014 OUTLANDER PHEV Workshop manual	CGFE14E1-CD(ENG) CGFF14E1-CD(FRE) CGFG14E1-CD(GER) CGFS14E1-CD(SPA) CGFI14E1-CD(ITA)	GENERATOR REMOVAL AND INSTALLATION (M549-33-010-01000-01)
Manual	Pub. No.	Applicable title (Info-ID)
2014 OUTLANDER PHEV Workshop manual	MMAL:AU900408 NZ:DRAFT	GENERATOR REMOVAL AND INSTALLATION (M549-33-010-02100-01)

3. Details :

See the attached document

※Time for enforcement : From the initial vehicle

GENERATOR

REMOVAL AND INSTALLATION

M1549330100010

⚠ DANGER

When servicing the high-voltage system parts, be sure to wear the specified protection equipment and disconnect the service plug to interrupt the high-voltage supply (Refer to P.54D-11).

Pre-removal and post-installation operation
Engine assembly removal and installation (Refer to GROUP 11C – Engine Assembly .)



<Deleted>

Removal steps

1. O-ring
2. Breather nipple
3. BREATHER HOSE
>>A<< 4. Clip
5. Front motor (electric motor unit) cable upper bracket
6. Front motor (electric motor unit) cable lower bracket
7. Wiring harness bracket
8. Wiring harness bracket
9. Generator
10. O-ring

<Deleted>

INSTALLATION SERVICE POINT

>>A<< CLIP INSTALLATION



The tabs of the clips should face towards the notches on the rear motor and the generator as shown.