SERVICE BULLETIN

MITSUBISHI MOTORS

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-13EXM54-501	DATE : 2013-04-16
SUBJECT : CORRECTION OF THE FUSE NUMBER		<Destination/Model> (G.EXP/GCC/EUR/MMNA/ THAILAND MIRAGE/SPACE STAR <M/Y> 13-14
GROUP : CHASSIS ELECTRICAL		

1. Description :

See the attached document for the correction of the error existing in the applicable service manual.

2. Applicable service manual :

<G.EXP/GCC/THAILAND>

Applicable manual	Pub. No.	Applicable title (INFO ID)	Content
2013 MIRAGE Workshop Manual	PWFE1201R THAILAND:DRAFT	CENTRALIZED JUNCTION (M901-00-034-19700-01)	Attached sheet 3

〈EUR〉

Applicable manual	Pub. No.	Applicable title (INFO ID)	Content
2013 SPACE STAR Workshop Manual	CA0E13E1-CD (ENG)	CENTRALIZED JUNCTION (M901-00-034-37900-01)	Attached sheet 3
	CA0F13E1-CD (FRE)		
	CA0G13E1-CD (GER)		
	CA0S13E1-CD (SPA)		
	CA0I13E1-CD (ITA)		

<MMNA>

Applicable manual	Pub. No.	Applicable title (INFO ID)	Content
2014 MIRAGE Service Manual (CD-ROM)	MSCD-016B-2014	CENTRALIZED JUNCTION (P.90-25) (M901-00-034-42100-01)	Attached sheet 3

3. Details :

See the attached document

Attached sheet 3

(in junction block)



ACB04352AB