MITSUBISHI MOTORS

# SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

| PURPOSE : CHANGE | ISSUE NO. : MSB-13EXML00-002 | DATE : 2013-07-31 | |
|---|---|---|---|
| SUBJECT : Clamping torque for brakes tube connection | | <Destination/Model> (AS SHONW BELOW)) | <M/Y> ALL |
| GROUP : GENERAL(Gr:00) | | | |

**1. Description :**

Please refer to the attached document for the information about the change of mention in the applicable service manual.

**2. Applicable destinations and models**

**MMNA/USTP:OUTLANDER/(CW0W)/OUTLANDER SPORT/RVR(GA0W)/LANCER(CY0A)/ LANCER SPORTBACK(CX0A)/LANCER EVO(CZ4A)**

**EUR :OUTLANDER/OUTLANDER-PHEV(CW0W/GF0W)/ASX(GA0W)/LANCER(CY0A)/ LANCER SPORTBACK(CX0A)/LANCER EVO(CZ4A)/4008(GB0W:PEUGEOT)/ C4 AIRCROSS(GC0W:CITROEN)**

**G.EXP:OUTLANDER(CW0W)/ASX(GA0W)/LANCER/LANCER-EX(CY0A)/LANCER EVOCZ4A)/DELICA D5(CV0W:JAPAN SEPC)**

**MMAL:OUTLANDER/OUTLANDER PHEV(CW0W/GF0W)/ ASX(GA0W)/LANCER(CY0A)/ LANCER SPORTBACK(CX0A)/LANCER EVO(CZ4A)**

**GCC:LANCER/LANCER-EX(CY0A)/ASX(GA0W)/LANCER-EVO(CZ4A)/OUTLANDER(CW0W)**

**3. About the details :**

Please refer to the attached document
MMNA/USTP : Attached sheet 2
Other destinations(EUR/G.EXP/GCC/MMAL) : Attached sheet 3

※ **Effective time : From the vehicle produced initially**

※ **Associated EO : QB0402**

Attached sheet 2






**<LH drive vehicles>**




**<RH drive vehicles>**




**<LH drive vehicles>**




**<RH drive vehicles>**

