MITSUBISHI MOTORS

SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-14E54-501	DATE : 2014-10-09
SUBJECT : Error in writing in the BMU service data		<DESTINATION/MODEL> (EUR) i-MiEV(HA3W) <M/Y> 15
GROUP : Gr:54(Chassis Electrical)		

1. Description :

Please refer to the attached document for the correction of the error in writing existing in the applicable service manual.

2. Affected service manuals :

Please refer to the following table

Applicable manual	Pub. No.	Applicable title (INFO ID)
2015 i-MiEV Workshop Manual	ENG: CHAE15E1-CD FRE: CHAF15E1-CD GER: CHAG15E1-CD SPA: CHAS15E1-CD ITA: CHAI15E1-CD	BMU DATA LIST REFERENCE TABLE (M549-45-550-12000-01)

3. About the details :

Please refer to the following table

Display on M.U.T.-III	Item No.	Inspection item	Inspection conditions	Value to be determined as normal
~~Capa. measured (MUT) comp. history~~ <Incorrect> ↑ Capa. measured (MUT) comp. history <Correct>	793	This historical KWP flag indicates how many times the system has measured the traction battery capacity successfully	When the system measures the traction battery capacity automatically	No flag or flag(s) is stored (This historical flag indicates how many times the system has measured the traction battery capacity successfully)